
SEPTEMBER 4, 2024 SUBMITTALS

2024-COA-226 (WD) 230 SOUTH PENNSYLVANIA STREET




INDIANAPOLIS HISTORIC PRESERVATION COMMISSION

CSX DESIGN REVIEW


SEPTEMBER, 2024




1925 HISTORIC PHOTO LOOKING SOUTHWEST




GEORGIA STREET ELEVATION - 1923





GROUND LEVEL FLOOR PLAN - 1923




THIRD LEVEL FLOOR PLAN - 1923





EXISTING BUILDING PHOTOS












CSX DESIGN REVIEW SITE CONTEXT





BOXCAR DEVELOPMENT LLC / INDIANAPOLIS HISTORIC PRESERVATION COMMISSION CSX DESIGNAREVIEW

CSX DESIGN REVIEW PROGRAM DIAGRAM



BOXCAR DEVELOPMENT LLC / INDIANAPOLIS HISTORIC PRESERVATION COMMISSION CSX DESIGNSREVIEW

















CSX DESIGN REVIEW EXTERIOR MATERIALS




CSX DESIGN REVIEW PENNSYLVANIA AVENUE STREETSCAPE




CSX DESIGN REVIEW GEORGIA STREET STREETSCAPE



CSX DESIGN REVIEW SCIOTO STREET STREETSCAPE



CSX DESIGN REVIEW HOTEL SOUTH ELEVATION



PROPOSED SHINOLA HOTEL - INDIANAPOLIS, INDIANA - FIRST NEW BUILD



SHINOLA HOTEL - DETROIT MICHIGAN - FLAGSHIP BUILDING









BOXCAR DEVELOPMENT LLC / INDIANAPOLIS HISTORIC PRESERVATION COMMISSION CSX DESIGN8REVIEW

CSX DESIGN REVIEW LOWER LEVEL 2






CSX DESIGN REVIEW LOWER LEVEL 1






CSX DESIGN REVIEW LEVEL 1






CSX DESIGN REVIEW LEVEL 2






CSX DESIGN REVIEW LEVEL 3



CSX DESIGN REVIEW TYPICAL GUESTROOM







CSX DESIGN REVIEW SKYPLANE EXPOSURE DIAGRAM




CSX DESIGN REVIEW SKYPLANE EXPOSURE - GEORGIA STREET SECTION



CSX DESIGN REVIEW SKYPLANE EXPOSURE - PENNSYLVANIA AVENUE SECTION





2023-COA-401 (OCH) & 2024-VHP-007 202 / 222 NORTH ALABAMA STREET

DATE	RECEIVED	CASE INFORMATION
		2023-COA-401 (OCH)
		COA NUMBER:
		202/222 N. ALABAMA STREET
		ADDRESS WHERE WORK IS TO BE DONE:
		Chase Smith, TWG
		APPLICANT NAME:
		September 4, 2024
		HEARING DATE:

222 N Alabama Street

Indianapolis, IN

August 01, 2024

North Alabama Redevelopment













© 2022 Smallwood, Reynolds, Stewart, Stewart & Associates, Inc. This drawing is the property of the architect and may not be used or reproduced without his written permission.



Table of Contents

Old City Hall & New Construction

Architectural Site Plan and Streetscapes

Architectural Floor Plans & Section

Architectural Building Elevations and Imagery

Old City Hall

Building Demolition Elevations

Architectural Building Elevations

Demolition Plans

Ceiling Demolition Plans

Architectural Floor Plans

Historic Architectural Elements

Interior Design Concepts


Architectural Site Plan & Streetscapes




















Closeup East Elevation

Old City Hall

Site Plan Layout Keynotes	
H01	CONCRETE PAVEMENT, 4"
H02	CONCRETE PAVEMENT, 8"
НО3	INTEGRAL CONCRETE CURB & WALK
H04	CONCRETE BARRIER CURB
H05	CONCRETE FLUSH CURB
H06	CONCRETE SWITCHBACK RAMP
H07	CONCRETE CURB RAMP
H08	UNIT PAVERS, TYPE 1
H09	UNIT PAVERS, TYPE 2
H10	UNIT PAVER CURB RAMP
H11	GRANITE STEP RESTORATION
H12	ASPHALT PAVEMENT
H13	STRUCTURAL SOIL EXTENTS
H14	GRANITE STEPS
H15	GRANITE PLANTER CURB
H16	bronze handrail
S01	LIMESTONE VENEER WALL, TYPE 1A
S02	LIMESTONE VENEER WALL, TYPE 1B
L01	LANDSCAPE AREA
F01	TREE GRATE
F02	DECORATIVE RAILING
F03	MOVEABLE TABLES AND CHAIRS
E01	SITE LIGHTING
E02	AES TRANSFORMER VAULT
X01	THERMOPLASTIC PAVEMENT MARKINGS
X02	PARKING METER POSTS










Closeup East Elevation

New Tower

Site Plan Layout Keynotes	
H01	CONCRETE PAVEMENT, 4"
H02	CONCRETE PAVEMENT, 8"
НО3	INTEGRAL CONCRETE CURB & WALK
H04	CONCRETE BARRIER CURB
H05	CONCRETE FLUSH CURB
H06	CONCRETE SWITCHBACK RAMP
H07	CONCRETE CURB RAMP
H08	UNIT PAVERS, TYPE 1
H09	UNIT PAVERS, TYPE 2
H10	UNIT PAVER CURB RAMP
нп	GRANITE STEP RESTORATION
H12	ASPHALT PAVEMENT
H13	STRUCTURAL SOIL EXTENTS
H14	GRANITE STEPS
H15	GRANITE PLANTER CURB
H16	bronze handrail
S01	LIMESTONE VENEER WALL, TYPE 1A
S02	LIMESTONE VENEER WALL, TYPE 1B
L01	LANDSCAPE AREA
F01	TREE GRATE
F02	DECORATIVE RAILING
F03	MOVEABLE TABLES AND CHAIRS
E01	SITE LIGHTING
E02	AES TRANSFORMER VAULT
X01	THERMOPLASTIC PAVEMENT MARKINGS
X02	PARKING METER POSTS











Closeup North Elevation

New York Street

Site Plan Layout Keynotes	
H01	CONCRETE PAVEMENT, 4"
H02	CONCRETE PAVEMENT, 8"
НО3	INTEGRAL CONCRETE CURB & WALK
H04	CONCRETE BARRIER CURB
H05	CONCRETE FLUSH CURB
H06	CONCRETE SWITCHBACK RAMP
H07	CONCRETE CURB RAMP
H08	UNIT PAVERS, TYPE 1
H09	UNIT PAVERS, TYPE 2
H10	UNIT PAVER CURB RAMP
H11	GRANITE STEP RESTORATION
H12	ASPHALT PAVEMENT
H13	STRUCTURAL SOIL EXTENTS
H14	GRANITE STEPS
H15	GRANITE PLANTER CURB
H16	bronze handrail
S01	LIMESTONE VENEER WALL, TYPE 1A
S02	LIMESTONE VENEER WALL, TYPE 1B
L01	LANDSCAPE AREA
F01	TREE GRATE
F02	DECORATIVE RAILING
F03	MOVEABLE TABLES AND CHAIRS
E01	SITE LIGHTING
E02	AES TRANSFORMER VAULT
X01	THERMOPLASTIC PAVEMENT MARKINGS
X02	PARKING METER POSTS











Site Layout Plan- Street Level

Layout Keynotes	
H01	CONCRETE PAVEMENT, 4"
H02	CONCRETE PAVEMENT, 8"
НО3	INTEGRAL CONCRETE CURB & WALK
H04	CONCRETE BARRIER CURB
H05	CONCRETE FLUSH CURB
H06	CONCRETE SWITCHBACK RAMP
H07	CONCRETE CURB RAMP
H08	UNIT PAVERS, TYPE 1
H09	UNIT PAVERS, TYPE 2
H10	UNIT PAVER CURB RAMP
H11	GRANITE STEP RESTORATION
H12	ASPHALT PAVEMENT
H13	STRUCTURAL SOIL EXTENTS
H14	GRANITE STEPS
H15	GRANITE PLANTER CURB
H16	bronze handrail
S01	LIMESTONE VENEER WALL, TYPE 1A
S02	LIMESTONE VENEER WALL, TYPE 1B
L01	LANDSCAPE AREA
F01	TREE GRATE
F02	DECORATIVE RAILING
F03	MOVEABLE TABLES AND CHAIRS
E01	SITE LIGHTING
E02	AES TRANSFORMER VAULT
X01	THERMOPLASTIC PAVEMENT MARKINGS
X02	PARKING METER POSTS















Site Layout Plan- Street Level

Layout Keynotes	
H01	CONCRETE PAVEMENT, 4"
H02	CONCRETE PAVEMENT, 8"
ноз	INTEGRAL CONCRETE CURB & WALK
H04	CONCRETE BARRIER CURB
H05	CONCRETE FLUSH CURB
H06	CONCRETE SWITCHBACK RAMP
H07	CONCRETE CURB RAMP
H08	UNIT PAVERS, TYPE 1
H09	UNIT PAVERS, TYPE 2
H10	UNIT PAVER CURB RAMP
нп	GRANITE STEP RESTORATION
H12	ASPHALT PAVEMENT
H13	STRUCTURAL SOIL EXTENTS
H14	GRANITE STEPS
H15	GRANITE PLANTER CURB
H16	bronze handrail
S01	LIMESTONE VENEER WALL, TYPE 1A
S02	LIMESTONE VENEER WALL, TYPE 1B
L01	LANDSCAPE AREA
F01	TREE GRATE
F02	DECORATIVE RAILING
F03	MOVEABLE TABLES AND CHAIRS
E01	SITE LIGHTING
E02	AES TRANSFORMER VAULT
X01	THERMOPLASTIC PAVEMENT MARKINGS
X02	PARKING METER POSTS






















Architectural Floor Plans & Section











Section A-A'





C4

C2









MECH.

CLUB HOUSE

POOL AMENITY

L 29

L 28


LEVEL 27


LEVEL 26

LEVEL 25 LEVEL 24

Basement Level

Level B-1











































































































Architectural Building Elevations & Imagery














East Elevation

Old City Hall & New Tower

Building Facade Materials	
Α	ARCH'L PRECAST CONCRETE
В	PARKING DECK SCREEN
B1	"FLEXFACADES" STRUCTURFLEX
B2	PERFORATED METAL
В3	METAL MESH
С	CURTAIN WALL
D	WINDOW WALL
E	INSULATED GLASS UNITS
E1	VISION 1 "Vertical Mass" Guardian SNR 50
E2	VISION 2 "Horizontal Mass" Guardian SNR 35
E3	VISION 3 "Darker" Guardian SNX 62/27, tinted
E4	SPANDREL Guardian SNR 50 with ceramic frit (#4)
E5	CLEAR Guardian SNX 70
F	COLUMN COVER / TALL SLAB EDGE COVER
F1	ACM
F2	FRP
F3	ARCH'L PRECAST CONCRETE
G	CIP CONCRETE PAINTED














North Elevation

Old City Hall & New Tower

Building Facade Materials	
Α	ARCH'L PRECAST CONCRETE
В	PARKING DECK SCREEN
С	CURTAIN WALL
D	WINDOW WALL
E	INSULATED GLASS UNITS
E1	VISION 1 "Vertical Mass" Guardian SNR 50
E2	VISION 2 "Horizontal Mass" Guardian SNR 35
E3	VISION 3 "Darker" Guardian SNX 62/27, tinted
E4	SPANDREL Guardian SNR 50 with ceramic frit (#4)
E5	CLEAR Guardian SNX 70
F	COLUMN COVER / TALL SLAB EDGE COVER
F1	ACM
F2	FRP
F3	ARCH'L PRECAST CONCRETE
G	CIP CONCRETE PAINTED













West Elevation

Old City Hall & New Tower

Building Facade Materials	
Α	ARCH'L PRECAST CONCRETE
В	PARKING DECK SCREEN
С	CURTAIN WALL
D	WINDOW WALL
E	INSULATED GLASS UNITS
E1	VISION 1 "Vertical Mass" Guardian SNR 50
E2	VISION 2 "Horizontal Mass" Guardian SNR 35
E3	VISION 3 "Darker" Guardian SNX 62/27, tinted
E4	SPANDREL Guardian SNR 50 with ceramic frit (#4)
E5	CLEAR Guardian SNX 70
F	COLUMN COVER / TALL SLAB EDGE COVER
F1	ACM
F2	FRP
F3	ARCH'L PRECAST CONCRETE
G	CIP CONCRETE PAINTED
Н	EXPOSED CONCRETE
1	CMU WITH PARGE FINISH
J	OVERHEAD DOOR
K	ALUMINUM LOUVERS













South Elevation

Old City Hall & New Tower

Building Facade Materials	
Α	ARCH'L PRECAST CONCRETE
В	PARKING DECK SCREEN
С	CURTAIN WALL
D	WINDOW WALL
E	INSULATED GLASS UNITS
El	VISION 1 "Vertical Mass" Guardian SNR 50
E2	VISION 2 "Horizontal Mass" Guardian SNR 35
E3	VISION 3 "Darker" Guardian SNX 62/27, tinted
E4	SPANDREL Guardian SNR 50 with ceramic frit (#4)
E5	CLEAR Guardian SNX 70
F	COLUMN COVER / TALL SLAB EDGE COVER
F1	ACM
F2	FRP
F3	ARCH'L PRECAST CONCRETE
G	CIP CONCRETE PAINTED





111
















Building Demolition Elevations Old City Hall

East Demolition Elevation

Old City Hall






E Ohio St








South Demolition Elevation





Elevation Demolition Keynotes			Scale: 1/16" = 1'-0"
1	DEMOLISH NON-HISTORIC LIMESTONE INFILL	6	DEMOLISH EXISTING RAMP AND RAILING
2	DEMOLISH NON-HISTORIC METAL GRILLE		
3	DEMOLISH SKYLIGHT GLAZING AND FRAME		
4	DEMOLISH NON-HISTORIC WINDOW		
5	DEMOLISH LIMSTONE SILL TO FINISH FLOOR		










West Demolition Elevation













North Demolition Elevation





Elevation Demolition Keynotes			Scale: 1/16" = 1'-0"
1	DEMOLISH NON-HISTORIC LIMESTONE INFILL	6	DEMOLISH EXISTING RAMP AND RAILING
2	DEMOLISH NON-HISTORIC METAL GRILLE		
3	DEMOLISH SKYLIGHT GLAZING AND FRAME		
4	DEMOLISH NON-HISTORIC WINDOW		
5	DEMOLISH LIMSTONE SILL TO FINISH FLOOR		











Architectural Building Elevations Old City Hall

East Elevation

Old City Hall





Eleve	ation Keynotes				Scale: $1/16'' = 1'-0''$	
1	1 DOUBLE HUNG ALUMINUM CLAD WOOD WINDOW		FIXED ALUMINUM CLAD WOOD WINDOW	11	existing cased window opening	
2	2 FIXED TRANSOM ALUMINUM CLAD WOOD WIN-		EXISTING METAL GRILLE AND LIMESTONE INFILL	12	EXISTING LIMESTONE INFILL AND CMU BACKUP TO	
	DOW		INFILL ROUGH OPENING WITH LIMESTONE TO MATCH		REMAIN	
3	ALUMINUM SKYLIGHT SYSETM	8		13	REPLACE EXISTING WINDOW TRIM PROFILE	
4	4 DOUBLE HUNG ALUMINUM CLAD WOOD WINDOW		existing bronze clad entrance door	14	ENLARGED EXISTING OPENING WITH NEW DOUBLE	
5	ENLARGED EXISTING OPENING.	10	DECORATIVE METAL GRILLE		DOORS	











202 N Alabama

South Elevation






Elev	ation Keynotes				Scale: 1/16" = 1'-0
1	DOUBLE HUNG ALUMINUM CLAD WOOD WINDOW	6	FIXED ALUMINUM CLAD WOOD WINDOW	11	EXISTING CASED WINDOW OPENING
2	FIXED TRANSOM ALUMINUM CLAD WOOD WIN-		7 EXISTING METAL GRILLE AND LIMESTONE INFILL	12	EXISTING LIMESTONE INFILL AND CMU BACKUP TO
	DOW		INFILL ROUGH OPENING WITH LIMESTONE TO MATCH		REMAIN
3	ALUMINUM SKYLIGHT SYSETM	8		13	REPLACE EXISTING WINDOW TRIM PROFILE
4	DOUBLE HUNG ALUMINUM CLAD WOOD WINDOW	9	9 EXISTING BRONZE CLAD ENTRANCE DOOR		ENLARGED EXISTING OPENING WITH NEW DOUBLE
5	ENLARGED EXISTING OPENING.	10 DECORATIVE METAL GRILLE —			DOORS





West Elevation












North Elevation

Old City Hall





Elev	ation Keynotes				Scale: 1/16" = 1'-0'
1	DOUBLE HUNG ALUMINUM CLAD WOOD WINDOW	6	FIXED ALUMINUM CLAD WOOD WINDOW	11	existing cased window opening
2	2 FIXED TRANSOM ALUMINUM CLAD WOOD WIN-		existing metal grille and limestone infill	12	EXISTING LIMESTONE INFILL AND CMU BACKUP TO
	DOW	_	INFILL ROUGH OPENING WITH LIMESTONE TO MATCH		REMAIN
3	ALUMINUM SKYLIGHT SYSETM	8		13	replace existing window trim profile
4	DOUBLE HUNG ALUMINUM CLAD WOOD WINDOW	9	9 EXISTING BRONZE CLAD ENTRANCE DOOR		ENLARGED EXISTING OPENING WITH NEW DOUBLE
5	ENLARGED EXISTING OPENING.	10 DECORATIVE METAL GRILLE -			DOORS









202 N Alabama


Demolition Plans Old City Hall

Basement Floor Demolition Plan

Old City Hall

Demo	olition Keynotes
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.
3	demolish non-historic stair.
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.
6	demolish non-historic coiling door.
7	demolish non-historic windown.
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGINAL HARDWOOD DOWN TO ORIGINAL WOOD, TILE , MARBLE.
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.
14	DEMOLISH WALL TILE DOWN TO ORIGINAL PLASTER.
15	demolish existing casework.
16	demolish non-historic ramp and railings.
17	SAWCUT AND DEMOLISH EXISTING SLAB.
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.
19	DEMOLISH EXISTING COLUMN.
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.
21	DEMOLISH NON-HISTORIC METAL GRILLE.
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.





202 N Alabama













First Floor Demolition Plan

Demo	olition Keynotes
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.
3	demolish non-historic stair.
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.
6	DEMOLISH NON-HISTORIC COILING DOOR.
7	DEMOLISH NON-HISTORIC WINDOWN.
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SAL- VAGED AND STORED.
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGINAL HARDWOOD DOWN TO ORIGINAL WOOD, TILE , MARBLE.
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.
14	DEMOLISH WALL TILE DOWN TO ORIGINAL PLASTER.
15	demolish existing casework.
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.
17	SAWCUT AND DEMOLISH EXISTING SLAB.
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.
19	DEMOLISH EXISTING COLUMN.
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.
21	DEMOLISH NON-HISTORIC METAL GRILLE.
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.
23	DEMOLISH PORTION OF EXISTING STAIRS FOR INSTALLATION OF NEW SWITCHBACK RAMP
24	DEMOLISH PORTION OF EXISTING STAIRS FOR INSTALLATION OF NEW SCULPTURE PLAZA

















Second Floor Demolition Plan

Demo	olition Keynotes
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.
3	DEMOLISH NON-HISTORIC STAIR.
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.
6	DEMOLISH NON-HISTORIC COILING DOOR.
7	DEMOLISH NON-HISTORIC WINDOWN.
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGINAL HARDWOOD DOWN TO ORIGINAL WOOD, TILE , MARBLE.
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.
14	DEMOLISH WALL TILE DOWN TO ORIGINAL PLASTER.
15	DEMOLISH EXISTING CASEWORK.
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.
17	SAWCUT AND DEMOLISH EXISTING SLAB.
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.
19	DEMOLISH EXISTING COLUMN.
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.
21	DEMOLISH NON-HISTORIC METAL GRILLE.
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.















Third Floor Demolition Plan

Demo	olition Keynotes
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.
3	demolish non-historic stair.
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.
6	DEMOLISH NON-HISTORIC COILING DOOR.
7	DEMOLISH NON-HISTORIC WINDOWN.
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGINAL HARDWOOD DOWN TO ORIGINAL WOOD, TILE , MARBLE.
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.
14	DEMOLISH WALL TILE DOWN TO ORIGINAL PLASTER.
15	demolish existing casework.
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.
17	SAWCUT AND DEMOLISH EXISTING SLAB.
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.
19	DEMOLISH EXISTING COLUMN.
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.
21	DEMOLISH NON-HISTORIC METAL GRILLE.
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.















Fourth Floor Demolition Plan

Demo	olition Keynotes
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.
3	DEMOLISH NON-HISTORIC STAIR.
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.
6	DEMOLISH NON-HISTORIC COILING DOOR.
7	DEMOLISH NON-HISTORIC WINDOWN.
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGINAL HARDWOOD DOWN TO ORIGINAL WOOD, TILE , MARBLE.
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.
14	DEMOLISH WALL TILE DOWN TO ORIGINAL PLASTER.
15	DEMOLISH EXISTING CASEWORK.
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.
17	SAWCUT AND DEMOLISH EXISTING SLAB.
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.
19	DEMOLISH EXISTING COLUMN.
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.
21	DEMOLISH NON-HISTORIC METAL GRILLE.
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.















Balcony/Attic Floor Demolition Plan

Demo	olition Keynotes
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.
3	DEMOLISH NON-HISTORIC STAIR.
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.
6	DEMOLISH NON-HISTORIC COILING DOOR.
7	DEMOLISH NON-HISTORIC WINDOWN.
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGINAL HARDWOOD DOWN TO ORIGINAL WOOD, TILE , MARBLE.
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.
14	DEMOLISH WALL TILE DOWN TO ORIGINAL PLASTER.
15	DEMOLISH EXISTING CASEWORK.
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.
17	SAWCUT AND DEMOLISH EXISTING SLAB.
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.
19	DEMOLISH EXISTING COLUMN.
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.
21	DEMOLISH NON-HISTORIC METAL GRILLE.
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.















Ceiling Demolition Plans Old City Hall

Basement Floor Ceiling Demolition Plan

Demo	olition Keynotes
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.
3	demolish non-historic stair.
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.
6	DEMOLISH NON-HISTORIC COILINBG DOOR.
7	demolish non-historic windown.
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGIONAL HARDWOOD DOWN TO ORIGIONAL WOOD, TILE , MARBLE.
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.
14	DEMOLISH WALL TILE DOWN TO ORIGIONAL PLASTER.
15	DEMOLISH EXISTING CASEWORK.
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.
17	SAWCUT AND DEMOLISH EXISTING SLAB.
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.
19	DEMOLISH EXISTING COLUMN.
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.
21	DEMOLISH NON-HISTORIC METAL GRILLE.
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.















First Floor Ceiling Demolition Plan

Demolition Keynotes		
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.	
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.	
3	demolish non-historic stair.	
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.	
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.	
6	DEMOLISH NON-HISTORIC COILINBG DOOR.	
7	DEMOLISH NON-HISTORIC WINDOWN.	
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SAL- VAGED AND STORED.	
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.	
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.	
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGIONAL HARDWOOD DOWN TO ORIGIONAL WOOD, TILE , MARBLE.	
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.	
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.	
14	DEMOLISH WALL TILE DOWN TO ORIGIONAL PLASTER.	
15	DEMOLISH EXISTING CASEWORK.	
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.	
17	SAWCUT AND DEMOLISH EXISTING SLAB.	
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.	
19	DEMOLISH EXISTING COLUMN.	
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.	
21	DEMOLISH NON-HISTORIC METAL GRILLE.	
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.	















Second Floor Ceiling Demolition Plan

Demolition Keynotes		
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.	
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.	
3	DEMOLISH NON-HISTORIC STAIR.	
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.	
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.	
6	DEMOLISH NON-HISTORIC COILINBG DOOR.	
7	DEMOLISH NON-HISTORIC WINDOWN.	
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.	
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.	
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.	
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGIONAL HARDWOOD DOWN TO ORIGIONAL WOOD, TILE , MARBLE.	
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.	
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.	
14	DEMOLISH WALL TILE DOWN TO ORIGIONAL PLASTER.	
15	DEMOLISH EXISTING CASEWORK.	
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.	
17	SAWCUT AND DEMOLISH EXISTING SLAB.	
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.	
19	DEMOLISH EXISTING COLUMN.	
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.	
21	DEMOLISH NON-HISTORIC METAL GRILLE.	
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.	















Third Floor Ceiling Demolition Plan

Old City Hall

Demolition Keynotes		
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.	
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.	
3	DEMOLISH NON-HISTORIC STAIR.	
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.	
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.	
6	DEMOLISH NON-HISTORIC COILINBG DOOR.	
7	DEMOLISH NON-HISTORIC WINDOWN.	
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.	
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.	
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.	
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGIONAL HARDWOOD DOWN TO ORIGIONAL WOOD, TILE , MARBLE.	
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.	
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.	
14	DEMOLISH WALL TILE DOWN TO ORIGIONAL PLASTER.	
15	DEMOLISH EXISTING CASEWORK.	
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.	
17	SAWCUT AND DEMOLISH EXISTING SLAB.	
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.	
19	DEMOLISH EXISTING COLUMN.	
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.	
21	DEMOLISH NON-HISTORIC METAL GRILLE.	
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.	





202 N Alabama











Fourth Floor Ceiling Demolition Plan

Demolition Keynotes		
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.	
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.	
3	demolish non-historic stair.	
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.	
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.	
6	DEMOLISH NON-HISTORIC COILINBG DOOR.	
7	DEMOLISH NON-HISTORIC WINDOWN.	
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.	
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.	
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.	
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGIONAL HARDWOOD DOWN TO ORIGIONAL WOOD, TILE , MARBLE.	
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.	
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.	
14	DEMOLISH WALL TILE DOWN TO ORIGIONAL PLASTER.	
15	DEMOLISH EXISTING CASEWORK.	
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.	
17	SAWCUT AND DEMOLISH EXISTING SLAB.	
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.	
19	DEMOLISH EXISTING COLUMN.	
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.	
21	DEMOLISH NON-HISTORIC METAL GRILLE.	
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.	














Roof Demolition Plan

Demolition Keynotes	
1	DEMOLISH NON-HISTORIC PARTITIONS AND DOORS, TYPICAL.
2	DEMOLISH FREIGHT ELEVATOR AND SHAFT WALLS.
3	demolish non-historic stair.
4	DEMOLISH NON-HISTORIC LIMESTONE AND CMU BACKUP WINDOW INFILL.
5	DEMOLISH ALL PLUMBING FIXTURES, PARTITIONS, AND ACCESSORIES.
6	demolish non-historic coilinbg door.
7	DEMOLISH NON-HISTORIC WINDOWN.
8	HISTORIC DOOR AND ASSOCIATED TRIM TO BE SALVAGED AND STORED.
9	DEMOLISH PORTION OF HISTORIC WALL. ANY ASSO- CIATED WOOD TRIM TO BE SALVAGED.
10	DEMOLISH PASSENGER ELEVATOR, SHAFT WALLS REMAIN.
11	DEMOLISH ALL CARPET, VINYL TILE, AND NON- ORIGIONAL HARDWOOD DOWN TO ORIGIONAL WOOD, TILE , MARBLE.
12	DEMOLISH ALL SUSPENDED ACOUSTICAL CEILING TILE CEILINGS.
13	DEMOLISH ALL NON-HISTORIC LIGHT FIXTURES.
14	DEMOLISH WALL TILE DOWN TO ORIGIONAL PLASTER.
15	DEMOLISH EXISTING CASEWORK.
16	DEMOLISH NON-HISTORIC RAMP AND RAILINGS.
17	SAWCUT AND DEMOLISH EXISTING SLAB.
18	DEMOLISH NON-HISTORIC DRYWALL CEILING.
19	DEMOLISH EXISTING COLUMN.
20	DEMOLISH SKYLIGHT GLAZING AND FRAME.
21	DEMOLISH NON-HISTORIC METAL GRILLE.
22	DEMOLISH LIMESTONE SILL AND PORTION OF WALL BELOW.













Architectural Floor Plans Old City Hall

Basement Floor Plan

Old City Hall





202 N Alabama










First Floor Plan









Second Floor Plan

Old City Hall





202 N Alabama











Third Floor Plan















Fourth Floor Plan

Old City Hall





202 N Alabama











Balcony / Attic Floor Plan















Roof Floor Plan

Roof Plan Keynotes		
1	NEW ALUMINUM SKYLIGHT SYSTEM	
2	NEW TPO ROOF	
3	NEW COPPER MANSARD ROOF	
4	NEW TPO ROOF AT LOWER FLAT ROOF AREAS	













Historic Architectural Elements Old City Hall

Historic Elements Strategy

Old City Hall

Floors

- Existing marble flooring in vestibule, rotunda, grand stair and side lobbies to be cleaned, repaired and restored.
- Existing wood flooring to be patched for stability. New flooring matching historical character to be installed where appropriate.
- Restroom, janitor and kitchen areas to receive new tile flooring to match historical character or use requirement.

Walls

- Existing stone, metal and wood balustrades to be cleaned, repaired and top handrail prepped for new finish.
- Marble columns, pilasters and wainscoting to be cleaned, repaired, restored.
- Existing rotunda scagliola finished columns to be cleaned, repaired, restored.
- Existing Verde marble column bases to be cleaned, repaired, restored.
- Existing painted murals by William F. Behrens on all floors in rotunda to be restored and protected
- Existing plaster walls to remain to be prepped for new finish, typical.

Openings / Trim

- Existing historic wood doors to be removed and hardware salvaged, where original.
- Where appropriate, new wood doors with historic stile, rail, and panel details to be installed.
- Existing wood base and chair-rail to be removed, salvaged, where original.
- New wood base and chair-rail to match existing historic profiles to be installed.
- Existing historic wood door frames/casings, where present, to be removed and salvaged.
- Where appropriate, new wood door frames/casings with historic profiles to be installed.
- New aluminum clad wood windows with historic profile, insulated glazing units, typical.

Ceilings

- Where exposed, all existing plaster moldings and coffers to be repaired and prepped for new finish.
- Where present, stone arches and stone mosaics at vaulted ceilings to be cleaned, restored.
- All existing, historic light fixtures to be removed, restored, and prepped for re-installation.
- Existing 'Tiffany Era' stained glass dome to be cleaned and repaired as necessary.










Historic Marble Floors

- Marble inlayed floor at grand stair landing.
- Marble inlaid floor at grand stair side 2. vestibule.
- Marble inlayed floor at grand stair / grand rotunda 1st floor landing.
- Marble inlayed floor at 1st floor side lobby.
- Marble inlayed floor at 2nd floor grand 5. rotunda.
- Marble inlayed floor at 1st floor main entrance vestibule.
- Marble inlayed 'compass' floor at 1st floor grand rotunda.
























Historic Floors

- Two layers of non-historic VCT over existing original terrazzo floor in basement main hall. Few small areas where terrazzo is exposed, shows severe signs of cracking / chipping.
- Non-original wood flooring in 3rd floor side exhibit hall. Existing door trim and casing was undercut to facilitate floor installation over original wood floor. Condition of existing wood floor unknown.
- Condition of original wood floor and trim at 1st floor side exhibit hall.
- Condition of original wood floor at 4th floor side exhibit hall. VCT glued over portions of floor, cementitious floor leveling compound used at transition.
- Condition of floor at 4th floor storage room. Original wood floor previously covered with VCT, followed by luan followed by carpet. Condition of existing wood floor unknown.
- Wood floor patching at 1st floor staff offices. Portions of demolished wood floor filled with cementitious floor leveling compound to smooth transition between wood and VCT
- Condition of original wood floor at 1st floor exhibit hall. Portion covered with glue down broadloom carpet, areas where previous walls existed infilled and patched with cementitious floor leveling compound.
- Original wood floor, damage shown consistent with majority of original wood floor in building.
- Existing terrazzo floor at door transition in basement. Right portion previously covered in cementitious floor leveler followed by VCT.

























Historic Marble Walls

Old City Hall

- 1. Existing scagliola column and banded 'egg and dart' motif column top.
- 2. Original marble columns and bases with full marble wainscoting in 1st floor entrance vestibule.
- 3. Existing painted wall mural by William F. Behrens in 1st floor grand rotunda above marble wainscoting and trim.
- 4. Existing painted wall mural by William F. Behrens in 2nd floor grand rotunda above marble wainscoting and trim.
- 5. Marble pilasters sitting on Verde marble base in 1st floor grand rotunda.
- 6. Existing marble wainscoting at 1st floor side lobby atop Verde marble base.
- 7. Existing scagliola columns and marble wainscoting at 4th floor grand rotunda, water damage in plaster moldings, scagliola finish and marble/plaster separation.



















AINENUE






Historic Trim & Windows

- 1. Non-historic refinish of existing wood chair rail and door casing. 'Orange peel' finish degradation seen typical of many refinished areas.
- 2. Missing / damanged historic chair rail and base molding.
- 3. Historic window casing trim with chair rail and base trim. Painted in various stages.
- 4. Exsiting wood casing, painted, atop original verde marble plinth block. Non original faux-marble base trim.
- 5. Existing arched wood casing, painted, on original verde marble plinth blocks. Original wood door and clerestory frame missing.
- 6. Existing arched wood casing, re-finished. Original wood door and clerestory frame missing. Existing base trim, painted.
- 7. Original wood window top and bottom sash, complete with hardware and ogee lugs. Existing window trim, damaged near sill, missing chair rail and base moldings.

























Historic Doors

Old City Hall

- 1. Existing wood door casing at 2nd floor side hall. Painted trim and cased opening infilled to create smaller opening, original door missing.
- 2. Existing wood door casing at 3rd floor side hall. Various levels of paint throughout previous tenants. Opening infilled to create smaller opening, original door missing.
- 3. Existing wood door casing, previously damaged and repaired with wood filler. Original door missing.
- 4. Existing wood door casing, portions painted and previously damaged. Original door missing.
- 5. Various original doors in random storage areas throughout the building.
- 6. Original wood door with original hardware intact. Original location of door unknown.
- 7. Original wood door and casing at 1st floor side stair entry. Non original hardware, likely swapped from a different door and center panel was cut to incorporate a louver, now no longer present.
- 8. Existing wood door casing with nonoriginal replacement door. Finish of casing suspected non-original.
- 9. Detail of original brass door hardware, missing top quarter-turn deadbolt. Door and frame finish suspected non-original.























Historic Ceilings

Old City Hall

- 1. Marble ribbed arches and mosaic web ceilings at 1st floor main entrance vestibule.
- 2. Historic light fixture in 1st floor main entrance vestibule.
- 3. Existing plaster moldings with leaf and Greek key motif in 2nd floor side lobby.
- 4. Existing plaster / wood crown detailing. Water damage typical of several locations.
- 5. Existing plaster / wood crown at 1st floor exhibit hall. Damage consistent with drop ceiling and mechanical attachment points.
- 6. Historic light fixture in 1st floor grand rotunda.
- 7. Condition of stained glass dome, view from attic.
- 8. 'Tiffany Era' glass dome, view from 4th floor rotunda balcony.
- 9. Existing salvaged historic light fixtures in various states of assembly.
- 10. Existing plaster / wood crown at 1st floor side hall. Damage consistent with electrical attachment points and previously installed mechanical equipment.





























Interior Design Concepts Old City Hall









Public Areas - Entry Vestibule & Lobby

Old City Hall

POISE
STYLIZED
VIBRANT
HISTORIC
MODERN



























Public Areas - Reception & Bar

Old City Hall

BOLD UNEXPECTED ROBUST VIBRANT DYNAMIC CONTRAST

Greeted by antiquity harmoniously woven with the spirit of dynamic modernity. The reception and bar area are inspired by the city hall's once temporary use as the central library. Bold marble, unexpected pops of color, wood paneling and casings punctuate the space inviting guests to lounge in comfort and style. Deep tones, wood accents, polished metals and rich textures reflect the energy of a bustling time in America fueled by innovation and fashion





















Restuarant Design Scheme

Old City Hall

CHIC

CHARMING

WHIMSICAL

FRESH

ARTISTIC

ELEGANT

















*Restaurant narrative to be further developed pending an operator




















Public Areas - Gallery & Pre Function

Old City Hall

INVIGORATING ECCENTRIC CULTIVATED RHYTHMIC GRACEFUL POLISHED



































202 N Alabama




AVENUE











©2022 Smallwood, Reynolds, Stewart, Stewart & Associates, Inc. 222127.00












List of Variances for 222 North Alabama Street

- *All Section references are to City of Indianapolis Consolidated Zoning / Subdivision Ordinance, last effective date of May 8, 2023.
- 1. Ch. 744, Art. IV, Sec.01.I., Figure 744-401-1: Parking bay dimension of 63 feet with 90 degree parking stalls required, proposed minimum bay dimension of 58 feet proposed (See Exhibits "A" and "B").
- 2. Ch. 744, Art. IV, Sec.01.I., Figure 744-401-1: Minimum drive aisle width for 2-way traffic (for standard size vehicles) of 23 feet required, 22 feet provided (See Exhibit "A").
- 3. Ch. 744, Art. IV, Sec.01.I., Figure 744-401-1: Standard vehicle stall dimensions of 9 feet by 20 feet required, standard vehicle stall size of 8.5 feet by 18 feet proposed (See Exhibit "B").
- 4. Ch. 744, Art. IV, Sec.01.I., Figure 744-401-1: Small vehicle stall dimensions of 8 feet by 16 feet required, minimum small vehicle stall size of 7.5 feet by 16 feet proposed (See Exhibit "B").
- 5. Ch. 744, Art. IV, Sec. 05.A., Table 744-405-1: 3 loading spaces for 400,000 500,000 square foot buildings in CBD-2 required; 2 loading spaces provided (See Exhibit "C").
- 6. Ch. 744, Art. IV, Sec. 05A, Table 744-405-1:
 Minimum dimension for loading spaces are 30 feet by 12 feet for first loading space, and 55 feet by 12 feet for each additional loading space required; minimum loading spaces of 10.33 feet by 35 feet proposed (See Exhibit "C").
- 7. Ch. 742, Art. I, Sec. 06.C.4.a.:

 Sky Exposure Plane Two requiring 60 degree incline from base centerline of Alabama Street to 200 feet, and thereafter at 90 degrees 75 degree incline to 200 feet and 90 degrees thereafter proposed (See Exhibit "D").
- 8. Ch. 744, Art. IV, Sec.02.C., Table 744-302-1:
 Minimum sidewalk width of 12 20 feet required along both Alabama and New York Street frontages; minimum sidewalk width of 8 feet on Alabama Street and minimum sidewalk width of 10 feet on New York Street proposed (See Exhibit "E").

1




DRIVE AISLE VARIANCE DIAGRAM

EXHIBIT A









P= Standard size space variance requested 8.5'x18'

C= compact (Small) size space 8'x16', 7.5'x16' minimum




PARKING VARIANCE DIAGRAM

EXHIBIT B









LOADING DOCK BERTH DIAGRAM


EXHIBIT C

















SKY EXPOSURE DIAGRAM

EXHIBIT D








Parking Angle	Vehicle Size	Curb Length (CL in figure)	Stall Width [1] (SW in figure)	Stall Length [2] (SL in figure)	Aisle Width (A in figure)	Direction of Travel
90°	Small vehicle	8 ft.	8 ft.	16 ft.	20 ft.	2-way
	Standard	9 ft.	9 ft.	20 ft.	23 ft.	2-way

ross floor area of:	
3	First berth 30 × 12; additional berths 55 × 12
	ross floor area of:



222 N Alabama


©2022 Smallwood, Reynolds, Slewart, Slewart & Associates, Inc.
This drawing is the property of the architect and may not be used or reproduced without his written permission.
222127.00 - TWG 222 N Alchama'\ 1.0 Graphics & Presentation\ 3.0 Presentation\ 3.0 Mility P Presentations \ 2024-02-24 IHPC Submittel\ 02 InD\ Versionse(Z) ind\ Versionse(Z).





5

2024-COA-241 (IRV) 5441 HIBBEN AVENUE



2024-COA-260 (IRV) 5270 EAST WASHINGTON STREET

We are requesting to resize the window on the left hand side of this picture. We would like to make it the same size as the one on the right hand side. The window on the right hand side appears to be the original window that was placed there. This is according to pictures that you can see the framing on the inside.

The window on the left is where the fire occurred that previously damaged the house. We have a new kitchen layout that should make the flow of that side of the house, interior wise, work better. And this change is also based on the fact that there was previous neglect in that area which has resulted in replacing much of the wood in that area. We've included a design layout of what the kitchen will look like.

It is important to note that outside of the window on the left is where the HVAC equipment is going to go. We plan on planting some bushes, or possibly a small fence with approval to cover up the HVAC equipment. By making the window smaller this will help draw away attention from the HVAC equipment. And since this is the side of the house that is facing the street, we're hoping to have the eyes drawn upwards towards the smaller window.

To be clear, the window is currently a 60" x 64" double window and we would like to make it a 28" x 39" double window, which is the same size as the one on the right.

In the report you'll see a picture of what the interior wood currently looks like. A design layout for the proposed kitchen. And a picture of the windows from the outside.





