## **DECEMBER 6, 2023** SUBMITTALS



# 2023-COA-252 (HMP) **2133 N. TALBOTT**





## $\frac{TALBOTT}{SCALE: 1/16'' = 1'-0''} STREET STREETSCAPE$

#### **RECEIVED**

#### November 17, 2023




## $\frac{T A L B O T T}{SCALE: 3/32'' = 1'-0''} S T R E E T S C A P E$

#### **RECEIVED**

#### November 17, 2023

ALLEY




TALBOTT STREET

#### **RECEIVED**

November 17, 2023


INDIANAPOLIS HISTORIC PRESERVATION COMMISSION 2133 N TALBOTT STREET SITE PLAN

SCALE: 1/16" = 1'-0"





#### November 17, 2023

#### ALLEY



#### November 17, 2023






#### November 17, 2023

**INDIANAPOLIS HISTORIC PRESERVATION COMMISSION** 


26'-Ø" ŀ EGRESS Δ Δ BENCH 84" × 54" SHOWER T SLOPE TO SLOPE TO 12'-0" PEAK 12'-0" PEAK <u>P. BDRM</u> 13'-7" × 14'-Ø" HDWD HDWD \* TILE <u>p. bath</u>  $11^{\prime}\text{-}6^{\prime\prime}\times12^{\prime}\text{-}10^{\prime\prime}$ TILE 72" × 32" <u>\@</u> VELUX-0 FREEST. TUB ΥÂΝ. KING SIZE BED 0 SKYLT C CØI VSE ∛g 2R/25 ₩ = = =LINEN W. D. TILE LAUNDRY 1R/25 P. CLOSET СРТ 12'-1Ø" × 8'-4" CPT Ц С  $\bigcirc$ 0 Ш \_\_\_\_ Ħ 2R/29 Ш -N \* <u>т</u> 0 0 72" VANITY <u>BATH 2</u>  $12^{-1} \mathcal{O}^{"} \times 5^{-9}$ TILE 13 14 15 16 17 18 ЩЩ 12 11 IR/25 40" H. HALF Щ 10 STAIRS DMDH BELOW WALL I HDWD <u>BDRM 2</u> 9 <u></u>4 <u>CLO.</u> 6'-0" x 5'-3" HDWD. LINEN ð 8 HALL || ||₹/26 BUILT-IN SHELVES, OPEN 10'-4" × 4'-7" ٦ HDWD 6 || <u>||</u> || <u>||</u> B FULL SIZE BED C NICHE <u>BDRM 3</u> Ü Ü 11'-2" × 10'-9" DRESSER HDWD. 5 U BDRM 2 Ш JONOSLOPE 11'-6" × 11'-9" LINE OF HDWD. Õ 10NOSL4 CLG. ABOVE l r T 

44'-0"




FULL SIZE BED





#### November 17, 2023






November 17, 2023




November 17, 2023





#### November 17, 2023









#### November 17, 2023




 2133 N TALBOTT STREET
 GARAGE WEST (BACKYARD) ELEVATION

 SCALE:
 1/4" = 1'-0"

RECEIVED

November 17, 2023




2 2133 N TALBOTT STREET SCALE: 1/4" = 1'-0" GARAGE SOUTH ELEVATION

#### November 17, 2023

INDIANAPOLIS HISTORIC PRESERVATION COMMISSION

= = =






3 2133 N TALBOTT STREET 3 SCALE: 1/4" = 1'-0" GARAGE EAST ELEVATION

November 17, 2023

INDIANAPOLIS HISTORIC PRESERVATION COMMISSION \_




4 2133 N TALBOTT STREET SCALE: 1/4" = 1'-0" GARAGE NORTH ELEVATION


November 17, 2023


INDIANAPOLIS HISTORIC PRESERVATION COMMISSION = = =


# 2023-COA-457 (IRV) 558 N. AUDUBON RD.
















DUE TO THE AGE OF THE ORIGINAL HOUSE AND THE NUMEROUS ADDITIONS AND CHANGES MADE TO THE ORIGINAL HOUSE THERE MAYBE UNFORSEEN ISSUES THAT ARRISE DURING THE CONSTUCTION AND PLANS AND STRUCUTRAL DESIGNS CONTAINED IN THESE PLANS MAY HAVE TO BE ALTERED. THE DESIGNERS (NPI CONSULTING LLC) ARE NOT RESPONSEBILE FOR UNFORSEEN CHANGES OR ALTERATIONS OR COSTS.


BEDROOM EGRESS

ALL BEDROOMS MUST HAVE ONE WINDOW FOR EMERGENCY ESCAPE

- MAXIMUM HEIGHT TO BOTTOM OF CLAR OPENING = 44" MINIMUM CLEAR WIDTH = 20"
- MINIMUM CLEAR HEIGHT = 24"
- MINIMUM CLEAR OPENING AREA = 5,7 6Q, FT,
- THE WINDOW SHALL BE OPERABLE FROM THE INSIDE NOT USING SPECIAL TOOLS OR KNOWLEDGE OR FORCE
- BEYOND THAT REQUIRED FOR ANY NORMAL WINDOW


	Å	-	3		
2338 Wednesd	ay, Septe	ember 6	5, 202	3	
			÷	ш	
			1/4" = 1	DRAWN BY: JNE	
			SCALE:	DRAWN	DATE:
				<u> </u>	
	_				
	RD.				
	Z				
	BO				
	DO	NDIANAP			
	AU	A			
	Z	D			
	28				
	Ŋ				
	N				
		r o Stru(		N	
NO OTHER TYPE	R (NPI CONSULTIN OF SERVICE IMPLIED. THESE P	-			Y.
COMPETENT LICENSED CONT WHO WILL	RACTOR KNOWLE	DGEABLE IN T	HE BUILD	ING TRAD	JES,
REPRESENTITIV THE CONTRACT FOR THE BUILDING CONS	OR AND THE OWNE	ER SHALL BE S	SOLEY RES	SPONSIBL	.E
THE DIMENSION THE BUILDING, I STRUCTURAL S	S INDICATE THE G S OF MAJOR ARCHITECT	URAL ELEMEN	NTS, AND 1	TYPE OF	
SUCCESSFULLY COMPLETING TH CONTRACTOR M	IE PROJECT. BASE IUST EMS REQUIRED FO	ED ON THE DR	AWINGS, T	ΉE	
4. THE CONTRAC DETERMINE THE SCOPE AND CONTRACTOR	CTOR MUST THROU	DOCUMENTS	AND DRA	WINGS. T	
ANY DISCREPAN OR OMISSIONS A DESIGNER.	S UNDER WHICH T ICIES ARE DISCOVED THE	E CONTRACTO	R MUST N	OTIFY TH	
EQUIPMENT, API AND SERVICES, COMPLETE THE A SAFE AND WO	AND PERFOM ALL	OPERATIONS	NECESSA	RY TO	
DO NOT SCALE DRAWINGS. 7. ALL MATERIA MANUFACTURE	LS AND EQUIPMEN RS INSTRUCTIONS	IT MUST BE IN	STALLED	PER	
AND RECOMMENDATIONS, AND TO THE BEST INDUSTRY STANDARDS. 8. THE DESIGNER AND HIS CONSULTANTS DO NOT WARRANT OR GUARANTEE THE ACCURACY AND COMPLETENESS OF THE WORK PRODUCT HEREIN. 9. ANY AND ALL SITE DRAWINGS HAVE BEEN FURNISHED TO THE					
LOCATION AND SITE PLANS FOR	CONSULTING LLC) ALL NEEDED R PERMIT PURPOSE FOR THE ACCURAC	ES, THE DESIG			
CONSULTING LL	ND HIS ASSOCIATE C, HE COST OF THE P			S THAT OF	<sup>-</sup> NPI
	DNSU	JLT	I N	G	
DESIGN DRAFTING					
	REND				
5089 New	Consultin Raesner Palestine	N. Dr.	63		
317-	509-1527 raftdesigr			า	





Д-2	4	)	
2338 Wednesday, September 6, 2	1/4 = 1		DATE:
558 N AUDUBON RD. INDIANAPOLIS			
ADMINISTRATION OF THE JOB WILL BE BY OWNER OF THE CONTRACTOR AND THE CONTRACTOR AND THE CONTRACTOR AND THE CONTRACTOR AND THE OWNER OF THE CONTRACTOR AND THE OWNER SHALL BE SOLEY	NG PL ISED UILDI NS AI	ANS ONL BY A ING TRAD ND BE	ES,
FOR THE BUILDING CONSTRUCTION PROCESS MEANS AND MET JOBSITE SAFETY. 3. THE DRAWINGS INDICATE THE GENERAL SCOPE OF THE DIMENSIONS OF THE BUILDING, MAJOR ARCHITECTURAL ELEMENTS, A STRUCTURAL SYSTEM. THE DRAWINGS DO NOT DESCRIBE ALL THE WORK R SUCCESSFULLY COMPLETING THE PROJECT. BASED ON THE DRAWIN CONTRACTOR MUST FURNISH ALL ITEMS REQUIRED FOR THE PROPER EXE COMPLETION OF THE WORK. 4. THE CONTRACTOR MUST THROUGHLY EXAMINE TH DETERMINE THE SCOPE AND INTENT OF THESE DOCUMENTS AND CONTRACTOR MUST VISIT THE SITE AND BECOME INFORMED OF ALL CONDITIONS, DIMENSIONS AND LIMITATIONS UNDER WHICH THE WORK IS TO BE ANY DISCREPANCIES	E DR. DRAN	PROJEC <sup>®</sup> IYPE OF RED FOR HE ION AND AWINGS 1 WINGS. T SISTING	ro He
OR OMISSIONS ARE DISCOVED THE CONTRACTOR MUDESIGNER. 5. THE CONTRACTOR MUST FURNISH SKILLED LABOR EQUIPMENT, APPLIANCES AND SERVICES, AND PERFOM ALL OPERATIONS NECE COMPLETE THE WORK IN A SAFE AND WORKMANLIKE MANNER. 6. NOTED DIMENSIONS TAKE PRECEDENCE OVER SCA DO NOT SCALE DRAWINGS. 7. ALL MATERIALS AND EQUIPMENT MUST BE INSTAL MANUFACTURERS INSTRUCTIONS AND RECOMMENDATIONS, AND TO THE BEST INDUSTI 8. THE DESIGNER AND HIS CONSULTANTS DO NOT WA GUARANTEE THE ACCURACY AND COMPLETENESS OF THE WORK PRODUCT HEREI 9. ANY AND ALL SITE DRAWINGS HAVE BEEN FURNISH DESIGNER AND ALTHOUGH THE	R, MAT ESSAI ALED I RY ST ARRA IN. IED T	TERIAL, RY TO DIMENSIO PER ANDARD NT OR O THE	DNS. S.
DESIGNER (NPI CONSULTING LLC) MAY HAVE DRAWN LOCATION AND ALL NEEDED SITE PLANS FOR PERMIT PURPOSES, THE DESIGNER RESPONSIBILE FOR THE ACCURACY OF THE SITE PLAN. 10. DESIGNER AND HIS ASSOCIATES LIABILITY AS WEI CONSULTING LLC, IS LIMITED TO THE COST OF THE PLANS. IS LIMITED TO THE COST OF THE PLANS.		DT 5 THAT OF	
DRAFTING RENDERING NPI Consulting LLC 5089 Raesner N. Dr. New Palestine, IN 46163 317-509-1527 npidraftdesign@gmail.c		۱	





<b>A-5</b>				
2338 Wednesday, September 6, 2023				
SCALE: 1/4" = 1' DRAWN BY: JNE DATE:				
558 N AUDUBON RD. INDIANAPOLIS				
B R O W N CONSTRUCTION				
1. THE DESIGNER (NPI CONSULTING LLC) IS PROVIDING PLANS ONLY. NO OTHER TYPE OF SERVICE IS INTENDED OR IMPLIED. THESE PLANS ARE TO BE USED BY A COMPETENT LICENSED CONTRACTOR KNOWLEDGEABLE IN THE BUILDING TRADES, WHO WILL CHECK AND VERIFY ALL DIMENSIONS AND CONDITIONS AND BE				
RESPONSIBLE FOR THEM. 2. ADMINISTRATION OF THE JOB WILL BE BY OWNER OR HIS REPRESENTITIVE. THE CONTRACTOR AND THE OWNER SHALL BE SOLEY RESPONSIBLE FOR THE BUILDING CONSTRUCTION PROCESS MEANS AND METHODS AND JOBSITE SAFETY. 3. THE DRAWINGS INDICATE THE GENERAL SCOPE OF THE PROJECT. THE DIMENSIONS OF THE BUILDING, MAJOR ARCHITECTURAL ELEMENTS, AND TYPE OF STRUCTURAL SYSTEM. THE DRAWINGS DO NOT DESCRIBE ALL THE WORK REQUIRED FOR SUCCESSFULLY COMPLETING THE PROJECT. BASED ON THE DRAWINGS, THE CONTRACTOR MUST FURNISH ALL ITEMS REQUIRED FOR THE PROPER EXECUTION AND COMPLETION OF THE WORK.				
4. THE CONTRACTOR MUST THROUGHLY EXAMINE THE DRAWINGS TO DETERMINE THE SCOPE AND INTENT OF THESE DOCUMENTS AND DRAWINGS. THE CONTRACTOR MUST VISIT THE SITE AND BECOME INFORMED OF ALL EXSISTING CONDITIONS, DIMENSIONS AND LIMITATIONS UNDER WHICH THE WORK IS TO BE PERFORMED. IF ANY DISCREPANCIES OR OMISSIONS ARE DISCOVED THE CONTRACTOR MUST NOTIFY THE DESIGNER.				
5. THE CONTRACTOR MUST FURNISH SKILLED LABOR, MATERIAL, EQUIPMENT, APPLIANCES AND SERVICES, AND PERFOM ALL OPERATIONS NECESSARY TO COMPLETE THE WORK IN A SAFE AND WORKMANLIKE MANNER. 6. NOTED DIMENSIONS TAKE PRECEDENCE OVER SCALED DIMENSIONS. DO NOT SCALE DRAWINGS.				
<ol> <li>ALL MATERIALS AND EQUIPMENT MUST BE INSTALLED PER MANUFACTURERS INSTRUCTIONS AND RECOMMENDATIONS, AND TO THE BEST INDUSTRY STANDARDS.</li> <li>THE DESIGNER AND HIS CONSULTANTS DO NOT WARRANT OR GUARANTEE THE ACCURACY AND COMPLETENESS OF THE WORK PRODUCT HEREIN.</li> <li>ANY AND ALL SITE DRAWINGS HAVE BEEN FURNISHED TO THE DESIGNER AND ALTHOUGH THE DESIGNER (NPI CONSULTING LLC) MAY HAVE DRAWN THE BUILDING</li> </ol>				
DESIGNER AND ALL NEEDED SITE PLANS FOR PERMIT PURPOSES, THE DESIGNER IS NOT RESPONSIBILE FOR THE ACCURACY OF THE SITE PLAN. 10. DESIGNER AND HIS ASSOCIATES LIABILITY AS WELL AS THAT OF NPI CONSULTING LLC, IS LIMITED TO THE COST OF THE PLANS.				
DRAFTING				
RENDERING NPI Consulting LLC 5089 Raesner N. Dr. New Palestine, IN 46163 317-509-1527 npidraftdesign@gmail.com				

# 2023-COA-458 (IRV) **332 LESLEY AVE.**



#### GENERAL

- 1. IT IS THE BUILDING OWNERS AND OR TENANTS RESPONSIBILITY TO REVIEW AND CHECK THE CONSTRUCTION DOCUMENTS PRIOR TO CONSTRUCTION AND VERIFY LOCATIONS, SIZES, QUANTITIES AND SPECIFIC MATERIALS USED IN CONJUNCTION WITH THE BUILDING OWNERS SPECIAL EQUIPMENT LAYOUT, USE OR FUNCTION.
- 2. THESE CONTRACT DOCUMENTS DO NOT ATTEMPT TO INSTRUCT THE CONTRACTOR IN THE SPECIFIC DETAILS OF THEIR TRADE.
- 3. WORK SHALL BE IN ACCORDANCE WITH THE QUALITY STANDARDS OF THE TRADE AND SHALL BE INSTALLED IN COMPLIANCE, AS A MINIMUM STANDARD, TO APPLICABLE LOCAL, STATE, FEDERAL CODES AND MANUFACTURER'S RECOMMENDATIONS.
- 4. WORK SHALL BE WARRANTED SATISFACTORY, IN MATERIALS AND WORKMANSHIP IN ACCORDANCE WITH THE CONTRACT DOCUMENTS.
- 5. THE DRAWINGS INDICATE THE GENERAL SCOPE OF THE PROJECT IN TERMS OF ARCHITECTURAL DESIGN CONCEPT, DIMENSIONS OF THE BUILDING AND MAJOR ARCHITECTURAL ELEMENTS. AS SCOPE DOCUMENTS, THE DRAWINGS DO NOT INDICATE OR DESCRIBE THE WORK REQUIRED FOR FULL PERFORMANCE AND COMPLETION OF THE REQUIREMENTS OF THE CONTRACT DOCUMENTS. ON THE BASIS OF THE GENERAL SCOPE INDICATED OR DESCRIBED. THE CONTRACTOR SHALL FURNISH THE ITEMS REQUIRED FOR THE PROPER EXECUTION AND COMPLETION OF THE WORK.
- 6. COMMENCING WORK BY A CONTRACTOR CONSTITUTES ACCEPTANCE OF THE CONDITIONS AND SURFACES CONCERNED. IF SUCH CONDITIONS OR SURFACES ARE UNACCEPTABLE, THE OWNER AND DESIGNER SHALL BE NOTIFIED IMMEDIATELY AND WORK SHOULD CEASE UNTIL THE UNACCEPTABLE CONDITIONS CAN BE REMEDIED.
- 7. THE COORDINATION OF THE MATERIALS, LABOR AND WORKMANSHIP IS THE SOLE RESPONSIBILITY OF THE CONTRACTOR TO INCLUDE ITEMS FURNISHED BY TENANT FOR CONTRACTOR INSTALLATION.
- 8. DIMENSIONS ARE TAKEN FROM THE FACE OF MASONRY WALLS, COLUMN CENTER LINES, FINISH FACE OF EXISTING WALLS AND/OR STUD FACE OF NEW WALLS UNLESS OTHERWISE INDICATED.
- 9. DO NOT SCALE DRAWINGS. REFER TO DIMENSIONS ILLUSTRATED ON DRAWINGS. NOTIFY THE DESIGNER OF DISCREPANCIES OR FOR CLARIFICATION.
- 10. THE CONTRACTOR SHALL ORDER AND SCHEDULE DELIVERY OF MATERIALS AND AMPLE TIME TO AVOID DELAYS IN CONSTRUCTION.
- 11. THE CONTRACTOR SHALL PROVIDE AND EXECUTE A WASTE MANAGEMENT PLAN IN COMPLIANCE WITH CURRENT LOCAL JURISDICTION REGULATIONS. AT A MINIMUM, THE CONTRACTOR SHALL REUSE OR RECYCLE AT LEAST 50% OF CONSTRUCTION DEBRIS GENERATED IF POSSIBLE.
- 12. THE CONTRACTOR SHALL EXAMINE AND BECOME FAMILIAR WITH ALL CONTRACT DOCUMENTS IN THEIR ENTIRETY. SURVEY THE PROJECT AND BECOME FAMILIAR WITH SCOPE OF WORK. ALL COSTS SUBMITTED SHALL BE BASED ON THOROUGH KNOWLEDGE OF ALL WORK AND MATERIALS REQUIRED. ANY DISCREPANCY AND OR UNCERTAINTY AS TO WHAT MATERIAL OR PRODUCT IS TO BE USED SHOULD BE VERIFIED WITH THE OWNER.
- 13. CONSTRUCTION SHALL COMPLY WITH APPLICABLE FEDERAL, LOCAL, AND STATE CODES AND ASSOCIATED AMENDMENTS.
- 14. THE CONTRACTOR SHALL BE SOLELY RESPONSIBLE FOR CONSTRUCTION MEANS, METHODS, TECHNIQUES, SEQUENCES, AND PROCEDURES REQUIRED FOR SAFE EXECUTION AND COMPLETION OF WORK AND FOR INITIATING, MAINTAINING, AND SUPERVISING ALL SAFETY PRECAUTIONS IN PROGRAMS IN CONNECTION WITH WORK.
- 15. ERRORS, OMISSIONS, OR INCONSISTENCIES ON THESE DRAWINGS OR VARIATIONS OR AMBIGUITIES BETWEEN THESE DRAWINGS AND ACTUAL SITE AND CONSTRUCTION CONDITIONS IN OUR REQUIREMENTS SHALL BE BROUGHT TO THE ATTENTION OF THE DESIGNER, IMMEDIATELY.
- 16. IN THE EVENT A DISCREPANCY IS FOUND IN THE CONTRACT DOCUMENTS, THE DESIGNER SHALL BE NOTIFIED IN WRITING IMMEDIATELY.
- 17. CONTRACTOR SHALL VERIFY DIMENSIONS IN THE FIELD AND NOTIFY THE 1 DESIGNER IN WRITING OF ANY DISCREPANCIES PRIOR TO CONSTRUCTION.
- 18. CONTRACTOR SHALL VERIFY MEASUREMENTS AT SITE AND BE RESPONSIBLE FOR ACCURACY AND CORRECTNESS OF SAME.
- 19. CONTRACTOR SHALL COORDINATE HIS WORK WITH E TRADES. NOTIFY DESIGNER OF ANY DISCREPANCIES PRIOR TO THE START OF CONSTRUCTION.
- 20. STORE MATERIALS IN CONDITIONS DESIGNATED BY MANUFACTURER SPECIFICATIONS.
- 21. REMOVE RUBBISH FROM PREMISES DAILY OR MORE FREQUENTLY AS DIRECTED
- 22. MATERIALS SHALL BE NEW AND SHALL BE INSTALLED IN STRICT CONFORMANCE WITH MANUFACTURERS INSTRUCTIONS AND/OR RECOMMENDATIONS UNLESS INDICATED OTHERWISE IN THE DRAWINGS AND SPECIFICATIONS
- 23. BRACE WALLS BETWEEN WORKDAYS AS NECESSARY TO GUARANTEE STABILITY.
- 24. DO NOT SCALE DRAWINGS.



### **AERIAL VIEW**

## 332 N LESLEY AVE. **INDIANAPOLIS, IN 46219**


### **DRAWINGS PROVIDED BY:**



WWW.DRAFTINGDESIGNSOLUTIONS.COM FACEBOOK.COM/DRAFTINGANDDESIGNSOLUTIONS LINKEDIN.COM/COMPANY/DRAFTING-DESIGN-SOLUTIONS 317.441.2812

GARAGE: TOTAL NON-LIVABLE:

## VICINITY MAP







## TABULATIONS:

**NON-LIVING AREA CALCULATIONS** 360 SQ. FT. 360 SQ.FT.

### **INDEX OF DRAWINGS**

TITLE	SHEET
PROJECT SUMMARY	A1
GARAGE PLANS	A2
GARAGE ELEVATIONS & SECTION	A3
SITE PLAN	C1




#### FOUNDATION NOTES

- 1. TYPICAL FOUNDATION WALL WILL BE 4" SLAB ON GRADE, 6" ABOVE FIN. GRADE.
- 2. TYPICAL FOUNDATION FOOTERS SHALL BE 16"WX8"D FOOTINGS, SEE DETAIL A/A3.
- 3. FOUNDATIONS TO BEAR A MINIMUM OF 12" BELOW FINISH GRADE 4. ALL ANCHOR BOLTS TO BE 5/8" DIA X 10 @ 32" O/C UNO.
- 5. ALL REINFORCING STEEL SHALL BE ASTM A-615, GRADE 60.
- 6. ALL REINFORCING STEEL TO OVERLAP A MINIMUM OF 24" FOR SPLICES. 7. PROVIDE CORNER BARS TO MATCH CONTINUOUS STEEL.
- 8. MINIMUM ALLOWABLE CONCRETE COMPRESSIVE STRENGTH SHALL BE 3000 PSI AT 26 DAYS. MAXIMUM AGGREGATE SIZE IS 1". MAXIMUM AIR ENTRAINMENT IS 3%. CEMENT SHOULD BE TYPE 1 OR 2.
- 9. SOIL BEARING CAPACITY ASSUMED TO BE 1500 PSF (UBC TYPE 4 SOIL). IF SOIL CONDITIONS VARY FROM THIS, THE PROJECT ENGINEER MUST BE NOTIFIED. ALL FOOTINGS MUST BEAR ON UNDISTURBED SOIL. ALL SLOPES MUST BE STABILIZED.
- 10. ADJACENT GROUND SURFACES SHALL BE SLOPED AWAY FROM STRUCTURE DRAINAGE OF SURROUNDING AREA SHALL ALSO BE PROVIDED TO PREVENT ACCUMULATION OF SOIL AND EROSION OF SOIL NEAR FOOTINGS.
- 11. UNIFORM SOIL CONDITIONS, MUST BE PROVIDED UNDER SLAB AND FOOTINGS. CUT/ FILL OR NON-UNIFORM SOIL CONDITIONS SHOULD BE EXCAVATED AND REPLACED W/ UNIFORM ENGINEERED FILL MATERIAL TO MINIMIZE DIFFERENTIAL MOVEMENT.

## WALL TYPE LEGEND

\_\_\_\_\_

GARAGE SLAB AT FOOTER, RECESSED 3-1/2" BELOW BOT. PL. SLOPE 1/4"/FT TOWARDS GARAGE DOOR OPENING





NUMBER	LA
D05	30
D07	160

### **FLOOR PLAN NOTES:**


1. ALL EXTERIOR DIMENSIONS ARE TO THE MAIN LAYER. DIMENSIONS TO OPENINGS ARE TO THE CENTERS. INTERIOR DIMENSIONS ARE TO THE STUDS. 2. CONTRACTOR SHALL VERIFY ALL DIMENSIONS AND IS RESPONSIBLE FOR ALL DIMENSIONS (INCLUDING ROUGH OPENINGS).


## **SCHEDULES**


DOOR SCHEDULE						
BEL	QTY	FLOOR	WIDTH	HEIGHT	DESCRIPTION	THICKNESS
68	1	1	36"	80"	EXT. HINGED-SLAB	1 3/4"
068	1	1	192"	80"	GARAGE-SLAB	1 3/4"


## WALL TYPE LEGEND

2X4X92-5/8" (PRE-CUT WALL STUDS @ 16" O.C). EXTERIOR WALL










INSTALLED WITHIN 30FT. OF THE TEMPORARY





#### WILLIAM M. NORMAN, P.E., S.

Professional Engineer - Structural Engineer

Professional and Structural Engineer licensed in Arizona, Florida, Indiana, Illinois (S.E.), Iowa, Kansas, Kentucky, Michigan, Mississippi, Missouri, Nebraska, North Carolina, South Carolina, Ohio, Pennsylvania, Tennessee, and Wisconsin <u>normantheengineer@yahoo.com</u>; c.317-650-3815

October 15, 2023

Ms. Kristina Smith Sent via email: <u>ebkbsmith@yahoo.com</u>

Re: Structural Conditions of Garage: Renovation 332 N Lesley Avenue Indianapolis, IN 46219

#### **STRUCTURAL ENGINEER'S REPORT**

On October 14, 2023, an inspection of the residential garage structure located at the above address was conducted to evaluate structural conditions for a potential renovation.

Digital images were taken during the inspection which will be retained in our digital file and some of these images are provided in this report. Level readings were taken using an 8 ft. Johnson beam level.

This residence was constructed in 1917, thereby being 106 years old. The garage structure does not appear to be original to the property, having 2x4 lumber and a split-faced hollow concrete block foundation.

This garage appears to have been constructed in the 1930's rather than at the same time as the residence. Additionally, it has been repaired several times using non-matching siding, lumber and other materials.



The original siding is in a dilapidated condition as the fasteners are rusting out, the siding is then detaching, there is decay, insect damage and varmint damage (see the images on the following page). The design of this structure is such that it RELIES ON THE SIDING FOR STRUCTURAL INTEGRITY. This is partly why the structure is significantly out of plumb.

The garage is leaning overall generally 1"-2" due to the siding deterioration:



Level readings indicate the north wall to be out of plumb by closely 3" and the rear (east) wall is also out of plumb by nearly 3" at the bottom, but this is due to the failing foundations. The block walls are being relied upon to hold back the soil of the garage floor. There is no floor slab to hold the blocks in place and there is no reinforcing for the masonry. The blocks are simply falling out. The foundation walls are bowed outward nearly 3" on the north and east sides.



As a consequence of the failing foundations, the walls are slipping off of the foundation block as there are no anchor bolts holding the sill plates to the foundations. Additionally, there is insect damage and decay to the sill plates (image above right). The front (west) garage door walls have inadequate headers that are sagging. The untreated wood walls (set on soil) and are deteriorating and loose. A new foundation is needed and the walls need to be attached to a foundation.



The southwest corner of the garage has sunken nearly 2" causing severe deformation of the wall, which is bowing and the siding is consequently detaching.



The interior was inspected and evidence of wood boring insects was evident and the structure wreaked of mold and fungus. The untreated wood has been in contact with the block masonry and the soil for decades causing decay.

The roof framing has been removed and replaced in the past but the top plate of the wall was damaged and was not replaced. The wood is compromised and decayed at many points where it appears there were previous rafters that were removed and there were roof leaks where water had been streaming along the rafters.

There should be a double top plate and there may have been one previously that has been removed (there are bolts at regular intervals that suggest there was once a double plate). The single top plate is a Code violation and leaves the walls more vulnerable to wall deformation.



The window on the south wall has been covered over with plywood as the glass is broken out. The window is out of square and the glass likely fractured out as a result of the wall deformation that had occurred (likely during strong winds after the siding had deteriorated). The garage is in a dilapidated condition and requires:

- new foundations as the existing foundations have failed and are falling out
- a floor slab that ties to the foundation walls
- foundation at the garage doors required
- proper garage door headers that span to the wall corners
- pressure treated lumber sill plates
- anchor bolts to secure the walls to the foundations
- new wall framing having bracing or sheathing as bracing (not siding as bracing)
- double top plate
- mechanical fasteners for the roof framing to the walls

Additionally, this structure is so severely deformed that re-alignment would be no be physically possible without causing additional structural damage. The foundation would then need be removed and replaced out from beneath the structure.

It is my recommendation that the structure is demolished and rebuilt. It is presently unsafe and the walls are about to move off of the foundation, which could occur at any time with strong wind. A collapse could be imminent and nothing of value should be stored in the garage.

Respectfully submitted,

M Nomm

William M. Norman, P.E., S.E. Licensed Professional Engineer and Structural Engineer License No. 19300350 State of Indiana

